



January 17, 2019 Photographs of Storm damage “King Tide” and Heavy Storm.
Pictures taken by Deputy Harbormaster Lane Tavasci of the storm debris/damage along Anchor Way.




ANCHOR WAY 1-17-19




ANCHOR WAY 1-17-19




ANCHOR WAY 1-17-19



ANCHOR WAY 1-17-19



ANCHOR WAY 1-17-19



ANCHOR WAY 1-17-19



ANCHOR WAY 1-17-19